

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NWSE

Location ID: 324155



Photo #8295 From entrance to location.



Photo #8297 Loadline open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NWSE

Location ID: 324155



Photo #8298 Location lacks stabilization.



Photo #8299 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NWSE

Location ID: 324155



Photo #8300 Insufficient tracking BMP at entrance to location.