


Inspection Photogs
Location Name: Padgett 32-6 4-2
Location ID: 333798



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Tank sign inspection photo, 6/24/22



IMG 04

Tank sign inspection photo, 11/8/22



IMG 05
Unused equipment



IMG 06
Sucker rods are unused equipment



IMG 07

Unused equipment/trash, 6/24/22



IMG 08

Unused equipment/trash, 11/8/22