

Final Reclamation and Stormwater Inspection

Date: 11/02/2022

Operator: MERIT ENERGY COMPANY - 56565

Location ID: 319665

Inspection Document #: 696105574

Adams County, CO

NENE Section 3 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bergman #1
Location ID: 319665



Photo 1. Taken from access road entrance, facing southeast. Photo illustrates location has not been reclaimed, per the Corrective Action, since the last inspection (Doc #696105344). The location remains unvegetated with evidence of bare soil and presence of noxious weeds (e.g. scotch and musk thistle) outlined in red.

Inspection Photos
Location Name: Bergman #1
Location ID: 319665



Photo 2. Taken from access road entrance, facing east. See comments in Photo 1.

Inspection Photos
Location Name: Bergman #1
Location ID: 319665



Photo 3. Taken from northern portion of location, facing south. Photo illustrates vehicle traffic observed on location.

Inspection Photos
Location Name: Bergman #1
Location ID: 319665



Photo 4. Taken from center portion of location, facing west. See comments in Photo 3.

Inspection Photos
Location Name: Bergman #1
Location ID: 319665



Photo 5. Close up photo taken from eastern portion of location. Photo illustrates CO List C Noxious Weed (e.g. Common Mullein).

Inspection Photos
Location Name: Bergman #1
Location ID: 319665



Photo 6. Taken from the center portion, facing west. Photo illustrates the CO List B Noxious weeds (e.g. Musk and Scotch Thistle) appears to have not been managed since identified in last inspection.