

# Final Reclamation and Stormwater Inspection

Date:11/08/2022

Operator: P O & G OPERATING LLC - 10634

Location ID: 324943

Inspection Document #: 696105576

Kit Carson County, CO

NWNW Section 21 T10S R45W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BEESON 4-21  
Location ID: 324943



**Photo 1.** Taken from the beginning of the EXISTING access road, facing west. This portion of the access road was identified in a previous inspection (FIR Doc #696105427) and Photo 1 (Inspection Photos Doc #696105444) stating that the access road has not been reclaimed. The pictured access road was built prior to any oil and gas development, see Photo 2, and does not need to be reclaimed by the operator.

Inspection Photos  
Location Name: BEESON 4-21  
Location ID: 324943



**Photo 2.** Google Earth aerial imagery taken circa 08/1993, illustrating access road was built prior to any oil and gas development (Well API# 063-06271, spud date of 09/03/1995). Red outline illustrates access road.

Inspection Photos  
Location Name: BEESON 4-21  
Location ID: 324943



**Photo 3.** Taken south of the access road “Y intersection”, facing south. Photo illustrates that the location’s access road has minimal contour and grading differences with the adjacent reference areas. The access road also appears to have achieved COGCC final reclamation vegetation standards (e.g. predominantly buffalo grass).

Inspection Photos  
Location Name: BEESON 4-21  
Location ID: 324943



**Photo 4.** Facing north from the northeastern portion of the location, see comments in Photo 3.

Inspection Photos  
Location Name: BEESON 4-21  
Location ID: 324943



**Photo 5.** Google Earth aerial imagery taken circa 06/2020, illustrating oil and gas access road that does not need to be reclaimed, outlined in red.