

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-67S96W /1NENW

Location ID: 324116



Photo #8319 From entrance to location.



Photo #8323 Loadline open ended.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-67S96W /1NENW

Location ID: 324116



**Photo #8320 Location lacks stabilization.**



**Photo #8322 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-67S96W /1NENW

Location ID: 324116



**Photo #8321 Insufficient tracking BMP at entrance to location.**