

**Comment:** Unused valve at separator (IMG 05). Unused 1/2" tubing at gas meter run (IMG 07). Unused 2" pipe at separator (IMG 06). Unused reflective wrap and pipe fitting at prime mover (IMG 04).

**Corrective Action:** All unused equipment must be returned to use or stored off location per rule 606. **Date:** 11/15/2022



Pictures from the INC showing the unused equipment found on location.





Pictures showing that all unused equipment has been removed from location.

Picture 1 shows the valve at the separator has been removed.

Picture 2 shows the unused 1/2 tubing has been removed

Picture 3 shows the 2" pipe has been removed

Picture 4 shows that the unused reflective wrap and pipe fitting have been removed.  
The dark spot is from the water on the reflective wrap. When it was picked up, the water ran off onto ground.