

Inspection Photos

API: 071-08114

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/8/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08114 | Date: 11/8/2022

Inspection Photos



Photo 1. Facing at the beginning of the access road. Sediment is accumulating in this area from erosion of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08114 | Date: 11/8/2022

Inspection Photos



Photo 2. There is erosion channels along this area of access road that need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08114 | Date: 11/8/2022

Inspection Photos



Photo 3. Facing toward the wellsite..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08114 | Date: 11/8/2022

Inspection Photos



Photo 4. Facing northeast overlooking the location.

