

# Inspection Photos

November 7, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335633

Location Name: CLOUGH-66S94W/16SENW

Inspection Document #: 702800899

Garfield County, CO

NENW Section 16 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: CLOUGH-66S94W/16SENW

Location ID: 335633



**Photo 1.** Photo shows production areas at the north of the Location.



**Photo 2.** Photo shows production areas at the south of the Location.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800899

Inspection Photos  
Location Name: CLOUGH-66S94W/16SENW  
Location ID: 335633



**Photo 3.** Photo taken from the northeast shows an overview of the interim areas. The vegetation community is dominated by perennial grasses with occasional shrubs.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800899