

Inspection Photos

November 7, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335636

Location Name: FEDERAL/RWF 12-9

Inspection Document #: 702800901

Garfield County, CO

NESE Section 8 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FEDERAL/RWF 12-9
Location ID: 335636



Photo 1. Photo taken from the southwest shows an overview of the Location.

Inspection Photos
Location Name: FEDERAL/RWF 12-9
Location ID: 335636



Photo 2. Photos taken from the northwest shows musk thistle (List B Noxious) in the interim area.



Inspection Photos
Location Name: FEDERAL/RWF 12-9
Location ID: 335636



Photo 3. Photo taken from the northwest shows a portion of the interim area with relatively high cover of cheatgrass (List C Noxious). Note establishment of seeded perennials in the rest of the interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800901

Inspection Photos
Location Name: FEDERAL/RWF 12-9
Location ID: 335636



Photo 4. Photo shows a portion of the western interim area, at the base of the slope where erosion degradation is occurring.



Photo 5. Photo shows where sediment laden stormwater flows have overtopped a wattle at the eastern perimeter of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800901

Inspection Photos
Location Name: FEDERAL/RWF 12-9
Location ID: 335636



Photo 6. Photos taken at the southeast of the Location shows a wattle installed along the downslope perimeter is not in proper functioning condition; stormwater has cut under the wattle, resulting in offsite degradation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800901

Inspection Photos
Location Name: FEDERAL/RWF 12-9
Location ID: 335636



Photo 7. Photos show a lack of stabilization/compaction degradation to the pad surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800901

Inspection Photos
Location Name: FEDERAL/RWF 12-9
Location ID: 335636



Photo 8. Photo shows interim areas at the west of the Location are overall stable at the time of this inspection. Initial establishment of seeded species is widespread.



Photo 9. Photo shows interim areas at the east of the Location are overall stable at the time of this inspection. Initial establishment of seeded species is widespread.