

## Eagle Hill 1-32 Supplemental Photos

**Photos 1-2:** Access road; Heavier cheat grass established in patches along the access road and heavily intermixed with native grasses.



**Photos 2-3:** Pad area - Heavier cheat grass established near northern perimeter and patches throughout.



**Photos 4:** Drainage area - sparse vegetation



**10/06/2022 EcoPoint Inspection Comments:** Vegetation along the access road is heavily intermixed with cheatgrass, some areas have a higher composition than others. Vegetation on pad area has patches of higher native grass species establishing, cheat grass is less dense near the center of disturbance. Roughly 2.34 ac were mapped to assist with identifying areas to interseed. Suggest additional interseeding at areas of slightly sparse vegetation on slopes where wattles have been installed.