

# Final Reclamation Inspection

September 3rd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 333292

Inspection Document #: 701900634

SWSE Section 24 T1N R68W

Corey McDonough  
Reclamation Contractor, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Totems 34-24  
Location ID: 333292



**Photo 1.** 2022 aerial imagery of the well pad. Tank battery highlighted in blue remains for the shut in Lawrence Totems 2 well API #123-08485.

Inspection Photos  
Location Name: Totems 34-24  
Location ID: 333292



**Photo 2.** Well pad falls within a fallow field. Site will remain in process until field is planted with crop and site can be re-inspected.