

Final Reclamation Inspection

September 3rd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 330879

Inspection Document #: 701900636

SESW Section 20 T2N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Succo 24-20
Location ID: 330879




Photo 1. 2022 aerial imagery of the well pad and tank battery.

Inspection Photos
Location Name: Succo 24-20
Location ID: 330879



Photo 2. Well pad and tank battery fall within a harvested field. Site will need to be re-inspected during the next growing season.