

# Final Reclamation Inspection

September 3rd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 327239

Inspection Document #: 701900647

SWSW Section 21 T4N R66W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Byron 13-21  
Location ID: 327239




Photo 1. 2021 aerial imagery of the well pad.

Inspection Photos  
Location Name: Byron 13-21  
Location ID: 327239



**Photo 2.** Well pad crop field has been harvested. Site will need to be re-inspected during the next growing season.

