

Final Reclamation Inspection

September 3rd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 332827

Inspection Document #: 701900649

SESW Section 29 T4N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McLeod 29-2
Location ID: 332827



Photo 1. 2021 aerial imagery of the well pad. Note: tank battery highlighted in blue remains for the producing McLeod 29-29X well API #123-24664.

Inspection Photos
Location Name: McLeod 29-2
Location ID: 332827



Photo 2. Overview photo taken at ground level from the northern edge facing south. Note: well pad falls in a bean crop field that is dominated by corn and barnyard grass. Appears consistent with adjacent reference area (see photo 3).

Inspection Photos
Location Name: McLeod 29-2
Location ID: 332827



Photo 3. Well pad reference area.

