

# Inspection Photos

November 7, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335637

Location Name: DOE-66S94W/9SWSW

Inspection Document #: 702800905

Garfield County, CO

SWSW Section 9 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: DOE-66S94W/9SWSW  
Location ID: 335637



**Photo 1.** Photo taken from the north shows an overview of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800905

Inspection Photos

Location Name: DOE-66S94W/9SWSW

Location ID: 335637



**Photo 2.** Photo shows the eastern interim areas of the Location are dominated by perennial grasses and shrubs.



**Photo 3.** Photo shows the western interim areas of the Location are dominated by perennial grasses and shrubs.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800905

Inspection Photos  
Location Name: DOE-66S94W/9SWSW  
Location ID: 335637



Photo 4. Photo shows production areas.



Photo 5. Photo shows production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800905