

# Inspection Photos

November 7, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335194

Location Name: LANGSTAFF-66S94W/16SWSW

Inspection Document #: 702800913

Garfield County, CO

SWSW Section 16 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: LANGSTAFF-66S94W/16SWSW  
Location ID: 335194



**Photo 1.** Photo shows northern production areas.



**Photo 2.** Photo shows southern production areas.



Inspection Photos  
Location Name: LANGSTAFF-66S94W/16SWSW  
Location ID: 335194



**Photo 3.** Photo shows tamarisk (List B Noxious) at the north of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800913

Inspection Photos

Location Name: LANGSTAFF-66S94W/16SWSW

Location ID: 335194



**Photo 4.** Photo shows interim areas at the north of the Location vegetated with perennial grasses and shrubs.



**Photo 5.** Photo shows interim areas at the south of the Location vegetated with sparse perennial grasses and shrubs.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800913