

# Final Reclamation Inspection

September 6th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 332061

Inspection Document #: 701900704

NENW Section 17 T5N R64W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission


Department of Natural Resources

Inspection Photos  
Location Name: Steinmetz 21-17  
Location ID: 332061




**Photo 1.** 2019 aerial imagery of the well pad and tank battery.

Inspection Photos  
Location Name: Steinmetz 21-17  
Location ID: 332061



**Photo 2.** Overview photo of the well pad, access road and reference area taken from the southern edge facing north using a drone. Note: well pad appears consistent with reference area.

Inspection Photos  
Location Name: Steinmetz 21-17  
Location ID: 332061



**Photo 3.** Overview photo of the tank battery and reference area taken from directly above the disturbance using a drone. Note: tank battery shows bare ground and stunted crop growth in the western half of the disturbance.

Inspection Photos  
Location Name: Steinmetz 21-17  
Location ID: 332061



**Photo 4.** Ground photo of the well pad/tank battery crop field.