

ARKOMA OPERATIONS LLC

Well Name:	Olson-Smith Unit 2 IGE 127	API #	067-07911 067-09545	Location ID #	311924
Inspector:	Alex Klink				
Date Inspected:	11/10/2022				
Date Submitted:	11/10/2022				
Document Number:	702500775				

Corrective Action 1:

Type	WEEDS		
Comment:	Weeds are established at separator (IMG 06).		
Corrective Action:	Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k	Date:	11/18/2022

Correction Action 1 Due:

11/18/2022

Action Completed:

11/11/2022

Action Taken:

Removed weeds that were established at the separators

BEFORE PHOTOS



AFTER PHOTOS



Corrective Action 2:

Type	STORAGE OF SUPL		
Comment:	400 bbl storage tank on north west corner of location is not in use (IMG 07 and IMG 08).		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.	Date:	12/11/2022

Correction Action 2 Due:

12/11/2022

Action Completed:

Week of 11/14/22

Action Taken:

Will be removed week of 11/14 when trucking can be lined up and moved to an upcoming workover.

BEFORE PHOTOS



IMG 07

Unused storage tank

AFTER PHOTOS

See above.

Corrective Action 3:

Type	OTHER		
Comment:	Lube oil at Olson Smith Gas Unit well is present on pump jack (IMG 05) and pooled on concrete (IMG 03).		
Corrective Action:	Remove lube oil and residue and dispose of in approved manner per rule 906 and 1002.f.	Date:	11/12/2022

Correction Action 3 Due:

11/12/2022

Action Completed:

11/11/2022

Action Taken:

Removed lube oil residue on concrete and disposed of it. Put pads and cleaner down.

BEFORE PHOTOS



IMG 03
Lube oil



IMG 05
Lube oil

AFTER PHOTOS



Corrective Action 4:

Comment:	Lube oil at Olson Smith Gas Unit well has impacted surface material (IMG 04).		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.	Date:	11/25/2022

Correction Action 4 Due:

11/25/2022

Action Completed:

11/11/2022

Action Taken:

Removed impacted material and disposed of it

BEFORE PHOTOS



IMG 04
Impacted material

AFTER PHOTOS

