

Inspection Photos
Location Name: Champlin 248 Amoco B#1
Location ID:319902



Photo#1 Production Tank & Produced Water Tank

Photo#2 Separator

Inspection Photos
Location Name: Champlin 248 Amoco B#1
Location ID:319902



Photo#3 PumpJack

Photo#4 **Leaking Gas below Master Valve**