

Inspection Photos
Location Name: Davis 32-13
Location ID:319861



Photo#1 Production Tank and Produced Water Tank



Photo#2 Separator

Inspection Photos
Location Name: Davis 32-13
Location ID:319861




Photo#3 **Bullplug Missing**



Photo#4 **Bullplug Missing**

Inspection Photos
Location Name: Davis 32-13
Location ID:319861



Photo#5 Pumjack and Wellhead

Photo#2