

# Final Reclamation Inspection

September 18th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 323104

Inspection Document #: 701900728

NWSE Section 1 T4N R64W

Corey McDonough  
Reclamation Contractor, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: FHA 10-1  
Location ID: 323104



**Photo 1.** 2020 aerial imagery of the well pad and tank battery.

Inspection Photos  
Location Name:FHA 10-1  
Location ID: 323104



**Photo 2.** Overview photo of the well pad and tank battery field. Field is dominated by Kochia and appears to be fallow. Site will need to be re-inspected when crop is planted.

