

Final Reclamation Inspection

September 18th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 310588

Inspection Document #: 701900739

NESE Section 17 T5N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hankins 17-DU
Location ID: 310588



Photo 1. 2020 aerial imagery of the well pad.

Inspection Photos
Location Name:Hankins 17-DU
Location ID: 310588



Photo 2. Well pad crop field is harvested. Site will need to be re-inspected during the next growing season.