

# Inspection Photos

November 8, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335615

Location Name: FEDERAL-66S94W/10NESW

Inspection Document #: 702800921

Garfield County, CO

NESW Section 10 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: FEDERAL-66S94W/10NESW  
Location ID: 335615



**Photo 1.** Photo shows production areas at the west.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800921



Inspection Photos  
Location Name: FEDERAL-66S94W/10NESW  
Location ID: 335615



**Photo 2.** Photo shows production areas to the east.



**Photo 3.** Photo shows production areas to the east.





## Inspection Photos

Location Name: FEDERAL-66S94W/10NESW

Location ID: 335615



**Photo 4.** Photo taken from the southern edge of the interim area shows a dense infestation of List B Noxious Weeds (bull, musk and Canada thistles).



**Photo 5.** Photo shows a bull thistle rosette in the northern interim area.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800921



Inspection Photos  
Location Name: FEDERAL-66S94W/10NESW  
Location ID: 335615



**Photo 6.** Photo shows rill erosion occurring on the road and pad surface.



**Photo 7.** Photo shows rill erosion in the slopes adjacent to the separators.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800921



Inspection Photos  
Location Name: FEDERAL-66S94W/10NESW  
Location ID: 335615



**Photo 8.** Photo shows lack of stabilization/compaction (ruts), rill erosion occurring in the road and pad surface and unstabilized cut slopes.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800921



Inspection Photos  
Location Name: FEDERAL-66S94W/10NESW  
Location ID: 335615



**Photo 9.** Photo shows the interim area to the northeast is dominated by perennial grasses.



**Photo 10.** Photo shows the interim area to the south is dominated by perennial grasses.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800921