

REC



LOCATION NENW 29, 35, 58u COUNTY Arroyo
OPERATOR Champlin COUNTY Adams
WELL NAME Downing 21-29-2 FORMATION _____

DATE OF INSPECTION DURING DRILLING: _____

RIG _____ SURFACE CASING: _____
BOP'S _____ DEPTH _____ WOC _____
CONTACT _____ CMT VOL _____ RETURNS _____
ADEQUATE AQUIFER PROTECTION? _____
COMMENTS _____

DATE OF INSPECTION AFTER COMPLETION: _____

FRACED: _____ PRODUCTION STRING: _____
CBL CHECKED? _____ DEPTH _____ STAGED _____
WATER DISPOSAL METHOD _____
PITS: PERMIT _____ TDS _____ SKIM TANK _____
DIMENSION: _____ SCREEN: _____ LINER: _____

LEASE SIGN: _____ TANK ID: _____ FENCED? _____
SURFACE EQUIPMENT: _____

DATE OF FINAL P&A INSPECTION 2/26/86

PLUG 1 SX @ 5980-6100 SURFACE RECLAIMED? Yes ✓
PLUG 2 SX @ 393-293 SITE CLEAN? Yes
PLUG 3 SX @ Surface LANDOWNER RELEASE? _____

INSPECTOR JSK

GOOD P&A, GOOD RESTORATION

P&A 7-9-85