

Inspection Photos

November 8, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335639

Location Name: CLOUGH-66S94W/10NWSE

Inspection Document #: 702800929

Garfield County, CO

NWSE Section 10 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/10NWSE
Location ID: 335639



11/8/22
+39.537877,-107.870772
284° W

Photo 1. Photo taken from the east shows an overview of the location.



Inspection Photos
Location Name: CLOUGH-66S94W/10NWSE
Location ID: 335639



Photo 2. Photo show anchor marker trash



Photo 3. Photo shows tank drain line missing a bull plug.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800929

Inspection Photos
Location Name: CLOUGH-66S94W/10NWSE
Location ID: 335639



Photo 4. Photo shows and overview of the bare, eroded cut slope at the south of the Location.



Inspection Photos
Location Name: CLOUGH-66S94W/10NWSE
Location ID: 335639



Photo 5. Photo shows exposed, undermined roots on the bare, eroded cut slope at the south of the Location.



Inspection Photos
Location Name: CLOUGH-66S94W/10NWSE
Location ID: 335639



Photo 6. Photo shows the reference area vegetation community just above the cut slope which stabilizes the comparatively gentle slope. The cut slope below is almost vertical, bare, eroding and contributing to degradation of the offsite vegetation community.



Inspection Photos

Location Name: CLOUGH-66S94W/10NWSE

Location ID: 335639



Photo 7. Photos show stormwater BMPs at the east of the Location. Bare exposed soils are prone to erosion and are resulting in high sediment loads.



Photo 8. Photos show stormwater BMPs at the east of the Location. Sediment trap is not in proper functioning condition; sediment has reached the level of the drain resulting in reduced ability for trap to settle sediment.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800929