

Final Reclamation Inspection

November 10, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 336611

Inspection Document #: 697504334

Weld County, CO

NESE Section 27 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: UPV-65N66W /27NESE
Location ID: 336611



Photo 1. Photo taken from central/western portion, facing North. Photo illustrates the surface owner has removed the previous supplies and the Operator has performed final reclamation activities.