

Inspection Photos

Location Name: Oxnard East 0607-8CH Spill

Location ID: 452516 Spill ID: 483258



Photo 1 Sign at production facility



Photo 2 Southwest corner of tank battery, looking east. Pea gravel ballast removed in foreground.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Oxnard East 0607-8CH Spill
Location ID: 452516 Spill ID: 483258



Photo 3 Southwest corner tank battery, dumpline piping.




Photo 4 Southwest corner tank battery



Inspection Photos
Location Name: Oxnard East 0607-8CH Spill
Location ID: 452516 Spill ID: 483258



Photo 5 Leak at fittings on crude oil tank load line



Photo 6 Leak at fittings on crude oil tank load line



Inspection Photos
Location Name: Oxnard East 0607-8CH Spill
Location ID: 452516 Spill ID: 483258



Photo 7 Staining around sump in northeast corner of tank battery



Photo 8 Damaged containment wall on north side of tank battery



Inspection Photos
Location Name: Oxnard East 0607-8CH Spill
Location ID: 452516 Spill ID: 483258



Photo 9 Standing liquid in containment at separator building



Photo 10 standing liquid inside separator building



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources