



Nov 8, 2022 12:27:05
+40.1018N -108.194

Inspection Photos
KT Resources LLC

3-inch HDPE produced water line
Spill/Release ID: 483021
Inspection Date: November 8, 2022

Un-fenced excavation with a 3-inch HDPE produced water line. Note the salt staining within the excavation and the stockpiles of apparent E&P impacted soil in the background of the photo.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Nov 8, 2022 12:28:57
+40.1019N -108.194

Inspection Photos

KT Resources LLC

3-inch HDPE produced water line

Spill/Release ID: 483021

Inspection Date: November 8, 2022

Un-fenced excavation with a 3-inch HDPE produced water line. Note the fluids and salt staining within the excavation. Note the stockpiles of apparent E&P impacted soil in the background of the photo



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
KT Resources LLC
3-inch HDPE produced water line
Spill/Release ID: 483021
Inspection Date: November 8, 2022

**Stockpiles of apparent E&P
impacted soil. Note the salt
staining.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Nov 8, 2022 12:29:45
+40.1019N -108.194

Inspection Photos
KT Resources LLC
3-inch HDPE produced water line
Spill/Release ID: 483021
Inspection Date: November 8, 2022

Area where fluids had migrated west of the spill/release area along an access road (red area). Note the stockpiles of apparent E&P impacted soil and the excavation in the background.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
KT Resources LLC
3-inch HDPE produced water line
Spill/Release ID: 483021
Inspection Date: November 8, 2022

**Area where fluids had migrated
west of the spill/release area along
an access road (red area).**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
KT Resources LLC

3-inch HDPE produced water line
Spill/Release ID: 483021
Inspection Date: November 8, 2022

Excavation with a 3-inch HDPE
produced water line. Note the
produced water discharging into
the excavation from the water line
(red area).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

KT Resources LLC

3-inch HDPE produced water line

Spill/Release ID: 483021

Inspection Date: November 8, 2022

Excavation with a 3-inch HDPE produced water line. Note the produced water discharging into the excavation from the water line (red area).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
KT Resources LLC

3-inch HDPE produced water line
Spill/Release ID: 483021
Inspection Date: November 8, 2022

Excavation with a 3-inch HDPE
produced water line. Note the
produced water discharging into
the excavation from the water line
(red area).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
KT Resources LLC
3-inch HDPE produced water line
Spill/Release ID: 483021
Inspection Date: November 8, 2022

**Stockpiles of apparent E&P
impacted soil. Note the salt
staining.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
KT Resources LLC
3-inch HDPE produced water line
Spill/Release ID: 483021
Inspection Date: November 8, 2022

**Stockpiles of apparent E&P
impacted soil. Note the salt
staining.**

Nov 8, 2022 12:30:35
+40.1020N -108.194



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
KT Resources LLC
3-inch HDPE produced water line
Spill/Release ID: 483021
Inspection Date: November 8, 2022

Stockpiles of apparent E&P
impacted soil. Note the salt
staining.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources