

Inspection Photos

November 8, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 322427

Location Name: CLOUGH-66S94W/13SENE

Inspection Document #: 702800937

Garfield County, CO

SENE Section 13 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/13SENE
Location ID: 322427



Photo 1. Photo shows satellite imagery of the location dated 6/3/2014. Note, roads and equipment footprints are evident indicating reclamation has not been performed.



Photo 2. Photo shows satellite imagery of the location dated 6/17/2016, nine days after the Operator indicated final reclamation corrective action was addressed. Imagery shows evidence of potential work around the wellhead (increase in bare ground/change in vegetation). The rest of the Location (in particular the equipment areas to the east remain unchanged).

Inspection Number: 702800937

Inspection Photos
Location Name: CLOUGH-66S94W/13SENE
Location ID: 322427




Photo 3. Photo shows satellite imagery of the location dated 2/21/2021. Roads and equipment footprints are still evident indicating reclamation (in particular gravel removal, compaction alleviation, road closure and seeding of the entire location was not performed. A large pile of rock remains (inset) seen on the imagery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800937

Inspection Photos
Location Name: CLOUGH-66S94W/13SENE
Location ID: 322427



Photo 4. Photo taken from north shows an overview of the western portion of the location.



Photo 5. Photo taken from north shows an overview of the eastern portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800937

Inspection Photos
Location Name: CLOUGH-66S94W/13SENE
Location ID: 322427



Photo 6. Photo shows an overview of the former well area from the north. Arrow indicates well marker. Note compacted, graveled pad.



Photo 7. Photo shows an overview of the former well area from the south. Arrow indicates well marker. Note compacted, graveled pad.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800937

Inspection Photos
Location Name: CLOUGH-66S94W/13SENE
Location ID: 322427



Photo 8. Photo shows a portion of the former equipment area at the east. Note compacted, graveled pad.



Photo 9. Photo taken from the center of the location disturbance. Note compacted, graveled pad.



Inspection Photos
Location Name: CLOUGH-66S94W/13SENE
Location ID: 322427



Photo 10. Photo taken adjacent to the well marker shows the area appears to have been seeded with perennial grasses. There is no other evidence of reclamation. Seeded species are sparse and restricted to a small area around the well.

