

# Final Reclamation Inspection

November 10, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 323313

Inspection Document #: 697504340

Weld County, CO

NWSW Section 25 T5N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: ANDERSON-COOMBS #4  
Location ID: 323313



**Photo 1.** COGCC GISOnline aerial imagery from 2015 illustrates active operations. Red circles are the well locations that the tank battery (orange circle) serviced. The well locations pass vegetation requirements but the tank battery fails.





Inspection Photos  
Location Name: ANDERSON-COOMBS #4  
Location ID: 323313



**Photo 2.** Photo taken from the well location, facing North. Photo illustrates perennial vegetation and location is now part of a mobile home park.



**Photo 3.** Photo taken from the well location, facing East. See comments under Photo 2.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697504340



Inspection Photos  
Location Name: ANDERSON-COOMBS #4  
Location ID: 323313



**Photo 4.** Photo taken from the associated tank battery, facing South. Photo illustrates the edge of reference with some perennials visible but then mostly annual tumbleweeds.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697504340



Inspection Photos  
Location Name: ANDERSON-COOMBS #4  
Location ID: 323313



**Photo 5.** Reference areas are everything inside the red line, facing West. Photo illustrates the establishment of perennials with annual tumbleweeds.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697504340