

Final Reclamation Inspection

November 10, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 322565

Inspection Document #: 697504342

Weld County, CO

NESW Section 25 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ANDERSON-COOMBS #1
Location ID: 322565




Photo 1. COGCC GISOnline aerial imagery from 2015 illustrates active operations. Red circles are the well locations that the tank battery (orange circle) serviced. The well locations pass vegetation requirements but the tank battery fails.



Inspection Photos
Location Name: ANDERSON-COOMBS #1
Location ID: 322565



Photo 2. Photo taken from the well location, facing North. Photo illustrates a dog park and location is now part of a mobile home park.



Inspection Photos
Location Name: ANDERSON-COOMBS #1
Location ID: 322565



Photo 3. Photo taken from the associated tank battery, facing West. Photo illustrates mostly annual tumbleweeds.



Photo 4. Reference areas are everything right of the red line, facing West. Photo illustrates the establishment of perennials with annual tumbleweeds.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697504342