



99999999

**ADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT**

- ☐ NOTICE OF UNSATISFACTORY INSPECTION
☒ NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100



API No. 05- 001 - 06101		LEASE NAME: Rico #1	
LOCATION: NWNW 32-35-59W		OPERATOR: Hewitt	
DATE: 11-7-96		INSPECTOR: EBB	
Insp. Type: HR	Insp. Status: 2A	PA: <input checked="" type="checkbox"/> N	Pass/Fail: <input checked="" type="checkbox"/> F
		Viol.: Y <input checked="" type="checkbox"/> N	NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	bond release	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	grass/cultiv-	
Miscellaneous		



00395987

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.