

Final Reclamation Inspection

November 10, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 323314

Inspection Document #: 697504344

Weld County, CO

SWNW Section 25 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ANDERSON-COOMBS #5
Location ID: 323314




Photo 1. COGCC GISOnline aerial imagery from 2015 illustrates active operations. Red circles are the well locations that the tank battery (orange circle) serviced. The well locations pass vegetation requirements but the tank battery fails.



Inspection Photos
Location Name: ANDERSON-COOMBS #5
Location ID: 323314



Photo 2. Photo taken from the well location, facing North. Photo illustrates location is now part of a mobile home park.



Photo 3. Photo taken from the well location, facing North. See comments under Photo 2.



Inspection Photos
Location Name: ANDERSON-COOMBS #5
Location ID: 323314



Photo 4. Photo taken from the well location, facing South. See comments under Photo 2.



Photo 5. Photo taken from the well location, facing West. See comments under Photo 2.

