

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 1 – Generator – WEEDS

Photo 2 – Generator – WEEDS

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 3 – Wellhead – Stained Soil

Photo 4 – Wellhead – Stained Soil

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 5 – WEEDS

Photo 6 – Wildlife Netting STILL MISSING

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 7 – Flare and ECD

Photo 8 – Gas Meter House

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 9 – Heater Treater

Photo 10 – Tank Battery

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 11 – Tank Battery Sign

Photo 12 – WEEDS in Interim Reclamation Area

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 13 – WEEDS in Interim Reclamation Area

Photo 14 – WEEDS in Interim Reclamation Area

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 15 – WEEDS in Interim Reclamation Area

Photo 16 – WEEDS in Interim Reclamation Area

Inspection Photos
Location Name: Cass Farms 11-25H
Location ID: 420020



Photo 17 – WEEDS in Interim Reclamation Area