

Final Reclamation Inspection

November 16, 2022

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 306144

Inspection Document #: 697504361

Weld County, CO

NWSW Section 26 T3N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: GREAT WESTERN 26-13

Location ID: 306144



Photo 1. Photo taken from the well location, facing West. Photo illustrates all equipment has been removed. Vegetation is a mix of perennial grasses and annual weeds throughout the location and reference areas.



Photo 2. Photo taken from the well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: GREAT WESTERN 26-13
Location ID: 306144



Photo 3. Photo taken from the well location, facing East. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: GREAT WESTERN 26-13
Location ID: 306144



11.16.2022 12:47

Photo 5. Photo taken from the associated tank battery, facing South. Photo illustrates vegetation is a mix of perennial grasses and annual weeds throughout the location.