

# Final Reclamation Inspection

November 16, 2022

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 333028

Inspection Document #: 697504363

Weld County, CO

NWSW Section 26 T3N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: GREAT WESTERN-66N67W 26NWSW

Location ID: 333028



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates all equipment has been removed. Vegetation is a mix of perennial grasses and annual weeds throughout the location. The location appears to be part of the industrial land use stormwater area.



**Photo 2.** Photo taken from the well location, facing Northwest. See comments under Photo 1.

Inspection Photos  
Location Name: GREAT WESTERN-66N67W 26NWSW  
Location ID: 333028



**Photo 3.** Photo taken from the associated tank battery, facing South. Photo illustrates vegetation is a mix of perennial grasses and annual weeds throughout the location.