

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER-66S92W /32SWNE

Location ID: 334901



Photo #8462 From entrance to location.



Photo #8464 From entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER-66S92W /32SWNE

Location ID: 334901



**Photo #8463 Flowline heating insulation open ended.**