

Final Reclamation Inspection

November 16, 2022

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 333241

Inspection Document #: 697504377

Weld County, CO

SWSE Section 26 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MERSHON-66N67W/26SWSE
Location ID: 333241



Photo 1. Photo taken from the location, facing South. Photo illustrates all equipment has been removed. Remediation activities appear to still be open; therefore, reclamation has not been performed.



Photo 2. Photo taken from the location, facing Southwest. See comments under Photo 1.

Inspection Photos

Location Name: MERSHON-66N67W/26SWSE

Location ID: 333241



Photo 3. Photo taken from the location, facing West. See comments under Photo 1.



Photo 4. Photo taken from the location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: MERSHON-66N67W/26SWSE
Location ID: 333241



Photo 5. Photo taken from the location, facing East. See comments under Photo 1.