

Final Reclamation Inspection

November 16, 2022

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 333062

Inspection Document #: 697504379

Weld County, CO

SENE Section 26 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: GREAT WESTERN-66N67W 26SENE

Location ID: 333062



Photo 1. Photo taken from the well location, facing South. Photo illustrates all equipment has been removed. Vegetation is a mix of perennial grasses and annual weeds throughout the location and reference areas.



Photo 2. Photo taken from the southern tank battery, facing East. See comments under Photo 1.

Inspection Photos

Location Name: GREAT WESTERN-66N67W 26SENE

Location ID: 333062



Photo 3. Photo taken from the southern tank battery, facing South. See comments under Photo 2.



Photo 4. Photo taken from the remainder of the tank battery location, facing West. Photo illustrates a land use change and equipment is now be stored at location.