

Final Reclamation Inspection

November 16, 2022

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 333057

Inspection Document #: 697504381

Weld County, CO

NENE Section 26 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GREAT WESTERN-66N67W 26NENE
Location ID: 333057




Photo 1. COGCC GISOnline 2019 aerial imagery. Photo illustrates the well location (red) and the associated offsite tank battery (orange). The tank battery was shared with Location ID 333062.



Inspection Photos

Location Name: GREAT WESTERN-66N67W 26NENE

Location ID: 333057



Photo 2. Photo taken from a portion of the well location access road, facing East. Photo illustrates perennial grasses established along the access road with mostly annual weeds throughout the reference areas.



Photo 3. Photo taken from the well location, facing North. Photo illustrates vegetation is a mix of perennial grasses and annual weeds throughout the location and reference areas.

Inspection Photos

Location Name: GREAT WESTERN-66N67W 26NENE

Location ID: 333057



Photo 4. Photo taken from the southern tank battery location, facing South. See comments under Photo 2.



Photo 5. Photo taken from the remainder of the tank battery location, facing West. Photo illustrates a land use change and equipment is now be stored at location.