

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403236788

Date Received:

11/21/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701900637

Inspection Date: 09/03/2022

FIR Submit Date: 11/11/2022

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 318461

Location Name: SUCCO GAS UNIT-62N66W Number: 20NESW County: _____

Qtrqr: NESW Sec: 20 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.120307 Longitude: -104.805080

FACILITY - API Number: 05-123- -00 Facility ID: 318461

Facility Name: SUCCO GAS UNIT-62N66W Number: 20NESW

Qtrqr: NESW Sec: 20 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.120307 Longitude: -104.805080

CORRECTIVE ACTIONS:

1 CA# 166068

Corrective Action: Comply with Rule 1004. Collaborate with the landowner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production. Provide documentation within the FIR Resolution form of when the corrective action work will be completed and provided date and documentation of coordination with the surface owner.

Date: 09/03/2022

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 09/03/2022

Satisfactory follow-up inspection document # 701900637 indicates location meets requirements. CA complete.

--

Comment: Satisfactory follow-up inspection document # 701900637 indicates location meets requirements. CA complete.

Print Name: Tyranny Bergin

Signed:

Title: Safety Representative

Date: 11/21/2022 4:58:35 PM

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Date Run: 11/21/2022 Doc [#403236788]