

Inspection Photos

November 16, 2022

Operator: Beeman Oil & Gas Inc - #7125

Location ID: 438580

Location Name: Welker 6-92 /1-2H11

Inspection Document #: 702800941

Moffat County, CO

SESE Section 2 T6N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Welker 6-92 /1-2H11
Location ID: 438580

11/16/22
+40.494060,-107.679575
274° W



Photo 1. Photo taken from the southeast shows an overview of the location.



Inspection Photos
Location Name: Welker 6-92 /1-2H11
Location ID: 438580



Photo 2. Photo shows stained soils.



Photo 3. Photo taken from the west of the pumpjack shows stained soils.

Inspection Photos
Location Name: Welker 6-92 /1-2H11
Location ID: 438580



Photo 4. Photo taken from the north of the Location shows a methanol tank. The secondary containment tank lacks wildlife protection BMPs. Safety labeling on the tank is faded and/or peeling and inadequate.



Photo 5. Photo taken from the well area shows a methanol tank lacking wildlife protection BMPs on the secondary containment device. Photo also shows unused equipment/debris.

Inspection Photos
Location Name: Welker 6-92 /1-2H11
Location ID: 438580



Photo 6. Photo shows a chemical tote without secondary containment and unused equipment/debris.



Photo 7. Photo shows an anchor marker in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800941

Inspection Photos
Location Name: Welker 6-92 /1-2H11
Location ID: 438580



Photo 8. Photo shows trash/debris and weed debris.



Photo 9. Photo shows trash/debris and weed debris.

Inspection Photos
Location Name: Welker 6-92 /1-2H11
Location ID: 438580



Photo 10. Photo shows trash/debris.



Photo 11. Photo shows trash/debris.

Inspection Photos
Location Name: Welker 6-92 /1-2H11
Location ID: 438580



Photo 12. Photo shows stained soils around the wellhead and trash/debris.

Inspection Photos
Location Name: Welker 6-92 /1-2H11
Location ID: 438580



Photo 13. Photo shows Scotch thistle (List B Noxious)



Photo 14. Photo shows diffuse knapweed (List B Noxious).

