

Inspection Photos

November 16, 2022

Operator: Beeman Oil & Gas Inc - #7125

Location ID: 425419

Location Name: Bret Grandbouche /24-02H

Inspection Document #: 702800942

Moffat County, CO

SESW Section 2 T6N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Bret Grandbouche /24-02H
Location ID: 425419



Photo 1. Photo taken from the northwest shows an overview of the Location.



Inspection Photos
Location Name: Bret Grandbouche /24-02H
Location ID: 425419



Photo 2. Photo shows the tank battery sign does not comply with Rule 605.e.



Photo 3. Photo shows staining within the tank battery secondary containment BMP.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800942

Inspection Photos
Location Name: Bret Grandbouche /24-02H
Location ID: 425419



Photo 4. Photos show trash.



Inspection Photos
Location Name: Bret Grandbouche /24-02H
Location ID: 425419



Photo 5. Photo taken from the northwestern cut slopes of the Location shows scotch thistle (List B Noxious). No evidence of weed management observed.



Inspection Photos
Location Name: Bret Grandbouche /24-02H
Location ID: 425419



Photo 6. Photo taken from the northeast of the Location shows interim reclamation has not been performed. The location still has large cut and fill slopes with a topsoil berm below, and a flat pad.




Photo 7. Photo shows satellite imagery of the unreclaimed location. Total disturbance area is approximately 5.2 acres.

Inspection Photos
Location Name: Bret Grandbouche /24-02H
Location ID: 425419



Photo 8. Photo taken from the northeast of the Location shows areas not needed for production operations where interim reclamation is required. Re-seeding alone is not sufficient. Interim reclamation is required.



Inspection Photos

Location Name: Bret Grandbouche /24-02H

Location ID: 425419



Photo 9. Photos shows cut slopes to the southwest of the Location where rill erosion is occurring. Although obscured by snow cover, rills are still evident. There is no evidence action have been taken to address erosion issues.



Photo 10. Photos shows cut slopes to the northwest of the Location where rill erosion is occurring.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800942

Inspection Photos
Location Name: Bret Grandbouche /24-02H
Location ID: 425419



Photo 11. Photos taken from the southwest shows two (2) unused risers.



Photo 12. Photos shows storage of supplies/equipment.