

Inspection Photos

November 16, 2022

Operator: Beeman Oil & Gas Inc - #7125

Location ID: 433805

Location Name: Bulldog /22-41V-890

Inspection Document #: 702800949

Moffat County, CO

Lot 1 Section 23 T8N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bulldog /22-41V-890
Location ID: 433805



Photo 1. Photo taken from the Location entrance shows an overview of the Location to the west.



Photo 2. Photo taken from the Location entrance shows an overview of the Location to the east.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800949

Inspection Photos
Location Name: Bulldog /22-41V-890
Location ID: 433805



Photo 3. Photo shows the tank battery sign (left) and wellhead sign (right) both lack the well API number. Photos also show vegetation and vegetation debris around production equipment.



Inspection Photos
Location Name: Bulldog /22-41V-890
Location ID: 433805



Photo 4. Photo shows bull thistle (List B Noxious Weed) which has gone to seed (left) and a first year rosette (right). There is no evidence that weed management has occurred.

Inspection Photos
Location Name: Bulldog /22-41V-890
Location ID: 433805



Photo 5. Photo taken from the southeast of the Location shows where the perimeter stormwater berm has been compromised and is not maintained in proper functioning condition.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800949