

Inspection Photos

Loc: 333870

Operator: SIMCOE LLC

Inspection Date: 11/16/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333870 | Date: 11/16/2022

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333870 | Date: 11/16/2022

Inspection Photos



Photo 2. Facing northeast at the location. There are displaced wattles that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333870 | Date: 11/16/2022

Inspection Photos



Photo 3. Facing southwest at the entrance of the location. This area has been cleaned up and reclaimed. There is a folded up tarp at red arrow that should be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333870 | Date: 11/16/2022