

Inspection Photos
Location Name: Tracy#1
Location ID:320197



Photo#1 Production Tank/Produced Water Tank

Photo#2 Separator/Gas Meter

Inspection Photos
Location Name: Tracy#1
Location ID:320197



Photo#3 Wellhead

Photo#4 **Corrective Action: No bull plug on Load out line**