

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403204395

Receive Date:

Report taken by:

## Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

### OPERATOR INFORMATION

Name of Operator: <u>KP KAUFFMAN COMPANY INC</u>	Operator No: <u>46290</u>	<b>Phone Numbers</b>
Address: <u>1700 LINCOLN ST STE 4550</u>		Phone: <u>(970) 261-3567</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80203</u>
Contact Person: <u>Craig Meis</u>	Email: <u>cmeis@kpk.com</u>	Mobile: <u>( )</u>

### PROJECT, PURPOSE & SITE INFORMATION

#### PROJECT INFORMATION

Remediation Project #: 14048 Initial Form 27 Document #: 402155631

#### PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☐ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☒ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☐ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: \_\_\_\_\_

#### SITE INFORMATION

No Multiple Facilities

Facility Type: <u>CENTRALIZED EP WASTE MGMT FAC</u>	Facility ID: <u>445769</u>	API #: _____	County Name: <u>JACKSON</u>
Facility Name: <u>Solid Waste Storage Facility</u>	Latitude: <u>40.823970</u>	Longitude: <u>-106.240840</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SENE</u>	Sec: <u>22</u>	Twp: <u>10N</u>	Range: <u>79w</u>
Meridian: <u>6</u>		Sensitive Area? <u>Yes</u>	

#### SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use Rangeland

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

#### Other Potential Receptors within 1/4 mile

0 habitable structures are within a quarter mile of the site; Jackson County Road 8b is 255 feet north of the site; SURFACE WATER: A tributary to Buffmeyer Draw is located approximately 1,200 feet northeast of the site across Jackson County Road 8b; Buffmeyer Draw is located approximately 2,250 feet north of the site. A USFWS-mapped riverine wetland (R4SBJ) is located adjacent to the east of the site. The 100 year floodplain is not located within 1/4 mile of the site; High Priority habitat is located over the site; a Greater Sage Grouse Lek Site buffer, Pronghorn Winter Concentration buffer, Greater Sage Grouse Priority Habitat Management Area buffer are located over the site, no Bald Eagle Roost sites or a Bald Eagle Active Nest sites are located around the site. CPW has stated the following restriction: Work should be scheduled outside of March 1 to July 15. A copy of correspondence has been provided. There are 0 domestic water wells within a quarter mile of the well.

## SITE INVESTIGATION PLAN

### TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☒ Oil ☐ Tank Bottoms
- ☐ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

### DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	TBD	Footprint of Solid Waste Storage Fac.

### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

E&P waste material, associated with Spill ID 200063899, has been collected and stored at the Solid Waste Storage Facility (Facility ID 445769). Removal of the E&P waste material is necessary prior to request for closure of the facility. Associated E&P waste has been removed from location and disposed of at the Walden Land Treatment Facility (Facility ID 427373).

### PROPOSED SAMPLING PLAN

#### Proposed Soil Sampling

- ☐ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

The total horizontal and vertical extent has not been established. Extent of impact will be based on limits of final excavation. 24 confirmation soil samples were collected as described in the Rule 915.e.(2) Guidance Document and analyzed for TPH (C6-C36), Table 915-1 Organic Compounds in Soil, Table 915-1 metals, and Table 915-1 Soil Suitability for Reclamation (Electrical conductivity, Sodium adsorption ratio, and pH by saturated paste method, boron (hot water soluble). 6 background soil samples were collected and analyzed for Table 915-1 metals and Table 015-1 Soil Suitability for Reclamation constituents. Additional confirmation soil samples will be collected after additional excavation is complete.

#### Proposed Groundwater Sampling

- ☐ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

If groundwater is encountered during excavation, a grab sample will be collected as soon as practical. If contaminated soil is in contact with groundwater or if free product/hydrocarbon sheen are observed, the release will be reported in accordance with Rule 912.b. Groundwater samples will be submitted for laboratory analysis of BTEX, naphthalene, 1,2,4-trimethylbenzene, and 1,3,5-trimethylbenzene by EPA Method 8260. A Groundwater Monitoring plan with a total of 5 wells, 1 upgradient, 2 cross gradient, 1 down gradient, and 1 at source (Additional wells may be necessary) will be submitted for approval, and Groundwater monitoring will continue until 4 clean consecutive quarters is achieved. COGCC will be provided a 72 Hour notice prior to the installation of Monitoring wells. Soil data will be collected. Boring and well construction logs will be completed and provided in a supplemental form 27.

#### Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

## SITE INVESTIGATION REPORT

### SAMPLE SUMMARY

Soil

NA / ND

Number of soil samples collected 32

Number of soil samples exceeding 915-1 32

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 2250

-- Highest concentration of TPH (mg/kg) 4300

-- Highest concentration of SAR 2.23

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 3

#### Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 915-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

#### Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

### OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☒ Were background samples collected as part of this site investigation?

6 background samples were collected on 9/14/2022 and analyzed for Table 915-1 metals and Table 915-1 Soil Suitability for Reclamation constituents.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☒ Is further site investigation required?

Additional excavation work is required followed by confirmation sampling.

### REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? Yes

#### SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

E&P waste material will be removed from location and brought to the Walden Land Treatment Facility (Facility ID 427373).

#### REMEDIAL ACTION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Excavation activities will resume July 15, 2023 to remove remaining impacted soils from excavation area due to weather and CPW constraints at the site. Soil sampling will be conducted to assess remediation progress. If samples are verified compliant with COGCC Table 915-1, request for closure of the remediation project will be submitted. If additional excavation is necessary based on results of collected samples, final excavation activities will be conducted during August 2023. Resampling will be conducted following final excavation activities.

#### Soil Remediation Summary

☐ In Situ

☒ Ex Situ

Bioremediation ( or enhanced bioremediation )

Yes Excavate and offsite disposal

Chemical oxidation

If Yes: Estimated Volume (Cubic Yards) 175

Air sparge / Soil vapor extraction

Name of Licensed Disposal Facility or COGCC Facility ID #

\_\_\_\_\_ Natural Attenuation  
\_\_\_\_\_ Other \_\_\_\_\_

No \_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ Land Treatment  
\_\_\_\_\_ Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Other \_\_\_\_\_

### **Groundwater Remediation Summary**

No \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
No \_\_\_\_\_ Chemical oxidation  
No \_\_\_\_\_ Air sparge / Soil vapor extraction  
No \_\_\_\_\_ Natural Attenuation  
No \_\_\_\_\_ Other \_\_\_\_\_

### **GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

If groundwater is encountered during excavation activities, a grab sample will be collected as soon as practical. If contaminated soil is in contact with groundwater or if free product/hydrocarbon sheen are observed, the release will be reported in accordance with Rule 912.b. Groundwater samples will be submitted for laboratory analysis of BTEX, naphthalene, 1,2,4-trimethylbenzene, and 1,3,5-trimethylbenzene by EPA Method 8260. A Groundwater Monitoring plan with a total of 5 wells, 1 upgradient, 2 cross gradient, 1 down gradient, and 1 at source (Additional wells may be necessary) will be submitted for approval, and Groundwater monitoring will continue until 4 clean consecutive quarters is achieved. COGCC will be provided a 72 Hour notice prior to the installation of Monitoring wells.

## REMEDATION PROGRESS UPDATE

### PERIODIC REPORTING

#### Approved Reporting Schedule:

☒ Quarterly☐ Semi-Annually☐ Annually☐ Other

#### ☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

#### Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☐ Other

### Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

KPK has sufficient insurance and bonding to fully address the anticipated costs of Remediation, including the remaining estimated costs for this project. KPK has general liability insurance and financial assurance in compliance with COGCC rules. The cost for remediation is a preliminary estimate only, costs may change upwards or downward based on site-specific information. KPK makes no representation or guarantees as to the accuracy of the preliminary estimate.

Operator anticipates the remaining cost for this project to be: \$ 8000

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

No beneficial use for soil or groundwater

Volume of E&P Waste (solid) in cubic yards 175

E&P waste (solid) description Hydrocarbon impacted soil

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility: Front Range Landfill

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

## REMEDATION COMPLETION REPORT

### REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

☐ Compliant with Rule 913.h.(1).

☐ Compliant with Rule 913.h.(2).

☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards?

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards?

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the COGCC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Upon receiving confirmation sample analytical that shows all impacts have been removed, KPK will submit request for Backfill to the state. Upon completion of the backfill KPK will consult with the landowner on seeding preference. Reclamation will commence following the 1000 series reclamation rules.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim

☐ Final

Did the Surface Owner provide the seed mix? No

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? No

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 09/04/2023

Proposed date of completion of Reclamation. 10/02/2023

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, or date of discovery. \_\_\_\_\_

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 05/20/2016

Proposed site investigation commencement. 05/20/2016

Proposed completion of site investigation. 08/15/2023

### REMEDIAL ACTION DATES

Proposed start date of Remediation. 07/15/2019

Proposed date of completion of Remediation. 08/31/2023

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☒ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

Analytical results from recent confirmation soil sampling indicates additional excavation and soil sampling is required.

**OPERATOR COMMENT**

Additional excavation followed by confirmation soil sampling is required in the former soil stockpile area based on analytical results from samples collected at 2 feet and 3 feet bgs. 2019 sampling analytical data has been provided and is referred to as the Cody Battery. The attached waste manifests are for excavated soil from below the former soil stockpile and are labeled Cody Battery. The former stockpile was removed from the site and disposed of at the Walden Land Treatment Facility (Facility ID 427373). Waste disposal totals on this form represent the excavated soil that has been disposed of. Prior dates on the implementation schedule section have not been entered because a release has not occurred. After consultation with CPW, work will not resume on the site until July 15, 2023 for priority habitat buffers.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Josiah Reamy

Title: Project Manager

Submit Date: \_\_\_\_\_

Email: PrimaryContractor@MarComLLC.net

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

Remediation Project Number: 14048

**COA Type****Description**

0 COA	

**Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

403230452	SITE MAP
403230454	SOIL SAMPLE LOCATION MAP
403230455	DISPOSAL MANIFESTS
403230457	CORRESPONDENCE
403230475	ANALYTICAL RESULTS
403230478	ANALYTICAL RESULTS
403230480	ANALYTICAL RESULTS

Total Attach: 7 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)