

# Inspection Photos

API: 067-09197

Operator: D J SIMMONS INC

Inspection Date: 11/18/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 033-09197 | Date: 11/18/2022

## Inspection Photos



**Photo 1.** South side of the location facing north. Perennial vegetation has established and reflects area levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 033-09197 | Date: 11/18/2022

## Inspection Photos



**Photo 2.** Center of the location facing north. Perennial vegetation has established and reflects area levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 033-09197 | Date: 11/18/2022

## Inspection Photos



**Photo 3.** Center of the location facing west. Perennial vegetation has established and reflects area levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 033-09197 | Date: 11/18/2022

## Inspection Photos



**Photo 4.** Center of the location facing south. Perennial vegetation has established and reflects area levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 033-09197 | Date: 11/18/2022

## Inspection Photos



**Photo 5.** Center of the location facing south. Perennial vegetation has established and reflects area levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 033-09197 | Date: 11/18/2022

## Inspection Photos



**Photo 6.** View of groundcover at the location which is reflective of reference area levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 033-09197 | Date: 11/18/2022

## Inspection Photos



**Photo 7.** Facing west toward the surrounding reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 033-09197 | Date: 11/18/2022