

COLORADO



99999999

# REGULATION COMMISSION REPORT


☐ NOTICE OF UNSATISFACTORY INSPECTION

 1120 Lincoln Street, Suite 801  
 Denver, CO 80203  
 (303)894-2100

☒ NOTICE OF SATISFACTORY INSPECTION

API No. 05-

001 - 6663

LEASE NAME:

Chumplin 113 Amos A-1-B

LOCATION:

NESE 23-35-59W

OPERATOR:

Walsh

DATE:

5-28-97

INSPECTOR:

EBB

Insp. Type:

PV

Insp. Status:

PV

PA: Y

N

Pass/Fail: P

F

Viol.: Y

N

NOV: Y

N

## INSPECTION ITEM

## COMMENTS

## INPUT

RECEIVED

## Well ID Signs

(Rule 210, 604.c(4))

✓

## Pits (Reserve/Production)

(Rule 902, 903, 904, 905)

pits -

## Fences

(Rule 603.b.7, 604.C.(3), 1002.A)

## Tank Battery Equipment

(Rule 603.b.3, 604)

2-300, VHT

## Fire Walls/Berms/Dikes

(Rule 603.b.12, 604)

## General Housekeeping

(Rule 603)

Pump off today

## Spills (Oil/Water)

(Rule 907)

## Bradenhead

(Rule 207.b)

## Drilling Well/Workover

(Rule 317)

## Surface Rehabilitation

(Rule 1002, 1003, 1004, 1103)

## Miscellaneous

## CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00416471