

Final Reclamation and Stormwater Inspection

Date: 11/16/2022

Operator: NOBLE ENERGY INC - 100332

Location ID: 320518

Inspection Document #: 696105594

Adams County, CO

SWNW Section 33 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Kimmel 12-33
Location ID: 320518



Photo 1. Taken from the eastern portion of the location, facing west. Photo illustrates several areas of non-uniform vegetation cover with undesirable vegetation observed (e.g. kochia).

Inspection Photos
Location Name: Kimmel 12-33
Location ID: 320518



Photo 2. Taken from the southern portion of the location, facing west. Photo illustrates an area approximately 20'x30' in size with evidence of road base/gravel and non-uniform vegetation cover.

Inspection Photos
Location Name: Kimmel 12-33
Location ID: 320518



Photo 3. Close up photo of road base/gravel from 20'x30' area.

Inspection Photos
Location Name: Kimmel 12-33
Location ID: 320518



Photo 4. Taken from the southern portion of the location, facing east. See comments in Photo 2.

Inspection Photos
Location Name: Kimmel 12-33
Location ID: 320518



Photo 5. Taken from eastern portion of the location, facing west. Photo illustrates area of non-uniform vegetation cover within the grass pasture.

Inspection Photos
Location Name: Kimmel 12-33
Location ID: 320518



Photo 6. Close up photo of undesirable vegetation (e.g. kochia) observed within red outline as referenced in Photo 5.

Inspection Photos
Location Name: Kimmel 12-33
Location ID: 320518



Photo 7. Taken from the western portion, facing east. See comments in Photo 5.

Inspection Photos
Location Name: Kimmel 12-33
Location ID: 320518



Photo 8. Taken from the northern portion, facing east. See comments in Photo 5.

Inspection Photos
Location Name: Kimmel 12-33
Location ID: 320518



Photo 9. Taken west of the location, facing northwest. Photo depicts reference area.